

1/15




FIG. 1




FIG. 2






FIG. 3



**FIG. 4**



**FIG. 5**

5/15




FIG. 6

50

GUN STRING 7:15a OK

GUNSTRINGID:

1	<input type="text"/>	8	<input type="text"/>	15	<input type="text"/>
2	<input type="text"/>	9	<input type="text"/>	16	<input type="text"/>
3	<input type="text"/>	10	<input type="text"/>	17	<input type="text"/>
4	<input type="text"/>	11	<input type="text"/>	18	<input type="text"/>
5	<input type="text"/>	12	<input type="text"/>	19	<input type="text"/>
6	<input type="text"/>	13	<input type="text"/>	20	<input type="text"/>
7	<input type="text"/>	14	<input type="text"/>	CONT.	<input type="text"/>

TEST SAVE HELP

408

FIG. 8

50

FIELD TESTER 7:14a OK

ADDRESSABLE SWITCH  
FIELD TESTER

WARNING: DETONATORS MUST NOT BE  
ATTACHED TO ANY GUN TO PERFORM

NEW  
LOAD  
DELETE

GUNSTEST HELP

56

400

406

402

404

FIG. 7

7:18a

DETONATOR WARNING

GUNSTRINGID: H1234

DETONATOR WARNING

1

2

3

4

5

6

7

WARNING VERIFY THAT NO  
DETONATORS ARE CONNECTED  
TO THE GUN STRING. PRESS  
OK TO CONTINUE WITH TEST;  
OTHERWISE, CLICK CANCEL

OK

CANCEL

13

20

14

CONT.

TEST

SAVE

HELP

FIG. 10

7:50a OK

FIELD TESTER

ADDRESSABLE SWITCH  
FIELD TESTER

WARNING: DETONATORS MUST NOT BE  
ATTACHED TO ANY GUN TO PERFORM

VIEW  
DELETE

TEST

HELP

FIG. 9

50

START

7:19a

GUNSTRINGID: H1234

414

1 ALIGN PDA AND FTB IR PORTS  
 2 THEN CLICK OK TO START THE  
 3 TEST OR CANCEL TO ABORT  
 4

OK

CANCEL

5

12

19

6

13

20

7

14

CONT.

TEST SAVE HELP

FIG. 11

50

START

7:20a

416

A TEST IS NOW IN PROGRESS, WHEN THE  
 FTB FLASHES ITS READY LIGHT, ALIGN THE  
 PDA AND FNB PORTS. CLICK CANCEL TO  
 ABORT.

CANCEL

FIG. 12



50

TEST (VIEW)

7:39a OK

430

GUNSTRINGID: H1234 10/17/01  
 OPERATOR: GARY  
 LOCATION: ROSHARON  
 NOTE: PDA REVIEW

1	1201	8	1208	15	120F
2	1202	9	1209	16	1210
3	1203	10	120A	17	1211
4	1204	11	120B	18	1212
5	1205	12	120C	19	1213
6	1206	13	120D	20	1214
7	1207	14	120E		CONT.

FIG. 14

50

TESTING COMPLETE 7:22a OK

418

PLEASE ENTER THE FOLLOWING TEST INFORMATION. CLICK ON OK WHEN DONE

420

STARTING GUN NUMBER: 422

424

OPERATOR: 428

426

LOCATION: 428

NOTE: 428

123	1	2	3	4	5	6	7	8	9	0	-	=	+
TAB	q	w	e	r	t	y	u	i	o	p	/		
CAP	a	s	d	f	g	h	j	k	l	;	'		
SHIFT	z	x	c	v	b	n	m	,	.	/			
CTL	ALT	?	%										

FIG. 13

START

7:45a

GUNSTRINGID: H1234

10/17/01

OPERATOR: GARY

LOCATION: ROSHARON

NOT

1 1

2 1

3 1

4 1204

5 1205

6 1206

7 1207

SAVE TEST ?

YES

NO

1204

1205

1206

1207

1208

1209

1210

1211

1212

1213

1214

CONT.

7:45a

FIG. 16

TEST (DETAIL VIEW)

7:40a OK

GUN ADDR: 120E

14

PASS/FAIL: FAIL

POWER-UP STATUS: PASS

WIRELINE FET: PASS

DETO. CIRCUITRY: FAIL

NOTE:

ERROR : DETO CIRCUITRY

TEST FAILED

7:40a OK

FIG. 15

11/15




FIG. 17

12/15




FIG. 18




FIG. 19




FIG. 21




FIG. 22



Creation date: 02-25-2004  
Indexing Officer: AAHMED4 - ASHA AHMED  
Team: OIPEBackFileIndexing  
Dossier: 09997021

Legal Date: 03-11-2003

No.	Doccode	Number of pages
1	CTRS	5

Total number of pages: 5

Remarks:

Order of re-scan issued on .....